

## **Solar Ponds Debris Removal - Notes to File**

To visually document current status of the debris removal project in-process photographs were taken on 2/5/98. These photos are labeled as 50400-15 & 50400-16. All photos are of the 207 A/B Corridor area. The photos were taken to show relative progress in this area. One can use the following photo references for comparison of status.

<b>Initial Characterization Study Photo #</b>	<b>Solar Ponds Debris Removal Photo #</b>
50400-15	50204-9 & 10
50400-16	50204-11 & 12

Status Update as of 02/25/98  
Bob Cathel, X6880, D4702

**ADMIN RECCRD**

1/4

Author WBirchfiel <WBirchfiel@aol.com> at inet  
Date 2/26/98 2 21 PM  
Priority Normal  
TO Bob Cathel at Mail4  
Subject Envirocare Question

----- Message Contents -----

Bob,

I asked Envirocare the question you raised about the pumps and larger pieces of debris from the Solar Pond project. Andy Drom (Envirocare's SME) said that the pumps and larger debris would be considered "Oversized Debris". Envirocare would place the debris in forms and fill with cement before disposal. This would meet the requirements of their Waste Acceptance Criteria. Envirocare would do this at their facility. If you have any questions, please let me know.

Wally Birchfiel



